

Karnataka State Fire And Emergency Services Department



Office of the District fire officer
Karnataka state fire and Emergency Services
Raichur Dire Station, Raichur-584102.



C.NO: 76/FSR/DFO/RCR/2026

Date:06/04/2026

"Fire Safety Recommendation"

ANNEXURE-I

Group-B Educational Building

"B1 And B2- Schools Up to Senior Secondary Level and other institutions"
NBC-2016, Part-4, Table 7 (11) 3. 1. 3 Group-B Educational Buildings

To,
The President
Rayara Krupa Education Trust (R)
Devadurga Taluk|| Devadurga,
Dist.Raichur-584111.

Sir/Madam,

Sub:- Issue of "Fire Safety Recommendation" to Rayara Krupa Education Trust (R) Devadurga Taluk|| Devadurga,Dist.Raichur-584111. Constructed Low Rise School Building Royal Kids International School Sy . S.No 53/* /1 Yaramasala Road Devaragudda Village, Taluk|| Devadurga, Dist.Raichur-584111.

Ref :- 1).C.No:20/INS/FSO/Devadurga/2026, Date:03/04/2026

2).Applicant Request Letter on Dated: 24/03/2026.

With reference to the subject above cited, the Premises to to Rayara Krupa Education Trust (R)Devadurga Taluk|| Devadurga,Dist.Raichur-584111. Constructed Low Rise School Building Royal Kids International School Sy . S.No 53/* /1 Yaramasala Road Devaragudda Village, Taluk|| Devadurga, Dist.Raichur-584111. has inspected by FSO Devadurga on Dated:- 01/04/2026 with respect to fire Prevention, fire fighting and evacuation measures to be complied premises and Submitted building details as under.

A. Details of the Building/Premises:-

01.	Name and Address of the applicant.	:	The President Rayara Krupa Education Trust (R)Devadurga Taluk Devadurga,Dist.Raichur-584111.
02.	Name and Address of the premises.	:	Royal Kids International School Sy . S.No 53/* /1 Yaramasala Road Devaragudda Village, Taluk Devadurga, Dist.Raichur-584111.
03.	Name and Address of the Building owner.	:	Shri Amareshwarao Shrishanakarrao Jagirdhar Pamankallur Village Taluk Devadurga Dist Raichur,
04.	Number of Buildings	:	01 No.
05.	Number of floor	:	Ground floor+ 2 upper Floors.
06.	Floor-wise details of occupancy :-		
	Ground Floor	:	1).Admission Cell-01No 2) Staff Room-01 No 3).Principal Chamber -01 No. 4).Chair man Office01 No 5).Class Room-10 No's



			6) Toilet's -01 No
	First Floor	:	1). Class Room-14 No's. 2). Staff Room-01 No . 3). Toilet Room-01 No
	Second Floor		1). Class Room-14 No's. 2). Staff Room-01 No . 3). Toilet Room-01 No
07	Height of the building	:	12.00 Mtrs.
08	Site area	:	8093.71 Sq.Mtrs.
09	Built-up area of each floor :-		
10	Ground Floor	:	1188.45 Sq.Mtrs.
	First Floor	:	1188.45. Sq.Mtrs.
	Second Floor	:	1188.45. Sq.Mtrs.
	Total built-up area	:	3565.35. Sq.Mtrs.
11	Surrounding properties:-		
	East(front)	:	Agriculture land
	West(rear)	:	Agriculture land
	North(side)	:	Agriculture land
	South(side)	:	Yaramasala Village Road
12.	Set back area available around the Building:-		
	East(front)	:	02.00 Mtrs.
	West(rear)	:	04.00 Mtrs.
	North(side)	:	80.00 Mtrs.
	South(side)	:	15.00 Mtrs.
	<u>Recommended</u> <u>To provide:</u> as per The Allowed Setback Shall be Kept from and Obstruction Further Construction Local Zonal Regulations.		

B. On inspection of this Institutional premises, the following fire prevention, fire fighting and evacuation measures recommended are considered absolutely essential from fire safety point of view :-

Sl.N o [01]	Details [02]	Existing [03]	Recommendations [04]
01.	Accessibility to Premises.	The premises are accessible from 05.00 Mtrs. Wide Yaramasala Village Road On Southern Side and the Road is hardened to carry the weight of 45,000 kgs.	Adequate.
02.	No of entrances.	01 No 04.00 Mtrs	-----
03.	No. of staircases available	No of staircase : 02 No.	--
		Width of staircase : 01.90Mtrs. 01.90Mtrs.	--
		Width of treads : 30 CM 30 CM	-----
		Height of risers : 14 CM 14 CM	
		No of riser per : 26 No's 26 No's	

		flight			
		Height of handrails	:	01.00	01.00
		Head room clearance	:	--	
04.	Portable Extinguisher	Not Provided.			<u>Recommended to Provided :-</u> Extinguishers as below mentioned 1).One ABC Type fire extinguisher each of 6 kg capacity For Every 100 m2. 2).One CO2 Fire Extinguisher of 4.5 kg Capacity shall be Provided near electrical Panel Board. [All the extinguishers suggested above should be with B.I. S markings and should be located at an easily accessible position without obstructing the normal passage and maintained periodically].
05.	First Aid Hose Reel Hose	Not Provided.			<u>Recommended to Provided :-</u> One Hose reel Hose required for every 1000 m2 of built up area and GI Pipe of minimum 63 mm shall be provided Hose Reel Hose of minimum 19 mm Size of adequate Length to reach the farthest point should be provided near the staircase at each floor with a shut off Branch having a Nozzle of 5 mm Size.
06.	Terrace tank Over Respective Tower Terrace	Not Provided			<u>Recommended to Provided :-</u> Terrace tank (RCC of FRP/under ground tank of 5000 Liters Capacity required with 450 LPM Booster pump, All the Fire Fighting pumps shall be Connected to alternative power supply (DG of Suitable Capacity).
07	At the terrace tank level With minimum Pressure of 3.5 kg/cm2	Not Provided			<u>Recommended to Provided :-</u> 01 No Of Pump With minium Pressure of 3.5 kg/sqcm
08.	Diesel Generator	Not Provided			<u>Recommended to Provided :-</u>15 KVA of Diesel Generator to Alternate Power Supply.
09.	Escape routes	Not Marked.			<u>Recommended To Provide</u> Direction in which the students have to move in the event of an emergency should be displayed in the corridor in each floor during evacuation.
10.	Fire order (Fire Safety Plans)	Not Displayed			<u>Recommended To Provide</u> The Notice board have been indicted the action should be taken by the employees in case of any emergency should be



			displayed with the telephone number of Devadurga Fire Station-08534-260101 and the telephone number of nearest Ambulance services and Police Station.
11.	No Smoking Board	Not Displayed	Recommended To Provide As per sec-4 of COPTA a board with words NO SMOKING AREA shall be written in English & Kannada both language shall be prominently displayed at inside the entry /exit of the each floor.
12.	Fire Siren	Not Installed	Recommended To Provide A Fire Siren shall installed in the premises to inform the inmates in case of a fire emergency and evacuate the area.
13.	Nominate one Fire Nodal Officer	Not yet Nominated	Recommended To Provide A fire nodal officer shall be nominated either from teaching or non teaching staff.
14	Nominate Fire Fighting Training	Not Imparted	Recommended To Provide At-least 40% of School Staff should be got trained in basic fire fighting at R.A. Mundkur fire & Emergency Services Academy, Bannerughatta road, Bangalore within 3 months or at an early date


Under the Circumstance stated above, there is No Objection to run Education activities in to **Rayara Krupa Education Trust (R)Devadurga Taluk|| Devadurga,Dist.Raichur-584111**. Constructed Low Rise School Building **Royal Kids International School Sy . S.No 53/* /1 Yaramasala Road Devaragudda Village, Taluk|| Devadurga, Dist.Raichur-584111**. School Building subject to the Condition of providing Additional Fire Fighting Equipments and Fire precautionary measures shown in Part-B. Therefore management should compulsory Karnataka Fire And Emergency Services Department conditions to provide Additional Equipments And Then Intimate to the office Within 90 days Positively Without Fail. **This Fire Safety Recommendation Certificate Valid for Only One Year From The date of issue and renewable without fail".**

School U-DISE Code:-For New Permission of School

To.

- 1).The DGP KSF&ES
Bangalore.
- 2).Fire Station Officer
Fire Station Devadurga

Your's faithfully


06/04/26
ಮಂಜುಳಾ ಶಿವಪ್ಪ ಮಂಜುಳಾ ಶಿವಪ್ಪ
ದಿವ್ಯಾಪುರ-584102